



Inspection report prepared forSam

Inspection of property at:

2nd Street Michigan June 2022





June 2022

Professional & Comprehensive Inspection

Sam

This is the summary of my inspection at 2nd Street in Michigan. This house appears to have been well built. As with all homes, ongoing maintenance is required. Repairs and improvements to the systems of the home will be needed over time. There are some items to bring to your attention.

- 1. There are four steps to the deck. This requires a handrail by code. If the deck is over 32" from the ground it requires a hand rail.
- 2. The cement board siding is broken up at the PVC pipe on the backside of the fireplace.



Page 2

3. The section of soffit around the lights on the back of the house is stained. There must be with a round the drip edge at that point.

4750 E. Fruitport Rd.
Fruitport, MI 49415

vanshomeinspectionservice

vanshomeinspectionservice @gmail.com

Ron Vander Velde



4. The whole house humidifier on the furnace is shut down for summer. It has leaked in the past. Watch it this fall when the heat is on and the humidifier is running.



Page 3

- 5. The slider screen door in the kitchen slides hard and comes out of the track.
- 6. The two retractable screen doors on the porch are torn loose at the top and do not retract.

- 7. The handle on the window in the shower on the main floor is broken.
- 8. Two of the skylight windows in the porch are missing the bottom trim piece inside the porch.



9. A piece of floor tile by the stove in the porch was not put in place by the outlet.



10. There is no protection to prevent a fall out of the two doors beside the fireplace. These doors are about two feet from the ground. There is no platform or steps.

Page 4

11. One smoke detector is missing the battery. I recommend having a carbon monoxide detector.

12. There is a minor build up on the drain pipe coming from the small side sink in the kitchen. This means moisture is getting through the joint and will eventually leak.



- 13. The drinking water faucet has no water supply. It's turned on at the Culligan unit down stairs. Filters may be dirty or something else is stopping the water flow.
- 14. The right front burner on the kitchen range is not lighting.
- 15. The disposal in the kitchen sink is very noisy.
- 16. The vent fan in the main floor bathroom doesn't suck enough air to hold a piece of toilet paper.

Thank you for using my service. If you have any questions please call/test or email me.

Ron Vander Velde

Ron Vander Velde

Here are a few tips for maintenance and upkeep to protect your investment.

- It is good for efficiency to have the furnace cleaned and adjusted at least every three years by a qualified licensed professional. The furnace filter should be changed every three months with regular use.
- 2. It is best to shut down and clean the humidifier at the end of the heating season so it is ready to turn on again in the fall. The damper lever on the pipe to the humidifier should be adjusted for summer or winter use.
- 3. It is good to have a winter cover for the air conditioning condenser. Keeping the fins clean will increase its life and improve its efficiency. If the condenser is covered, turn off the power at the breaker box so that it is not accidently cycled with the cover on. This would over heat the motor and condenser.
- 4. Extended down spouts and or splash guards are ways to keep water from entering the ground by the foundation. Gutter guards will help keep the debris out that may clog up the gutters or down spouts.
- 5. You have a nice deck. Keeping it clean will increase its life and maintain its good appearance.
- 6. Before using a wood/pellet burning fireplace or stove it is recommended a licensed professional cleans and evaluates the chimney and unit for safety and efficiency.
- 7. Most manufacturers of water heaters recommend they be drained at least once a year to prevent mineral build up. This increases the life of the water heater and it will heat the water more efficiently. This can be drained to the sump pump by hose.
- 8. Check the dryer vent once a year to see that there is no lint build-up.
- 9. Keeping the area clear around your main water shutoff and electrical panel are helpful if you need to access them quickly in case of an emergency or safety situation.
- 10. Test the smoke detectors every six months. On battery type detectors change the battery every six months, and annually for hard wired detectors. Use a day such as your birthday or mark it on your calendar each year to remind you to do this. Install smoke detectors on each level of your house and one outside or inside of all sleeping areas. Manufacturers recommend replacing battery type detectors every five years and hard wired detectors every ten years for your safety.
- 11. Rekeying or replacing exterior lock sets is a good security improvement when moving into your home.
- 12. General upkeep: When something breaks or is not functioning correctly repair it so that it does not become a nuisance or have a possibility to cause damage.

Thank you again for the opportunity to serve you.

Checklist Index

Maintenance Tips	6
1. GROUNDS	8
2. FOUNDATION / EXTERIOR / ROOF / INSULATION	9
3. HEATING/COOLING	11
4. PLUMBING	12
5. ELECTRICAL	13
6. INTERIOR	14
7. GARAGE/LAUNDRY	15
8. KITCHEN	16
9. MAIN FLOOR BATHROOM	17
10. UPPER BATHROOM	18

1. GROUNDS

	DESCRIPTION	DEFICIENCY	RECOMMENDATION
SITE			
Plantings	good		
Driveway	concrete		
Sidewalks	stone		
Retaining walls	stone		
Grading	good		
DECK			
Location	back		
Structural support	4x4 & 4x6		
Surface materials	composite decking		
Steps	good		
Railings	4 steps to deck	none/requires a hand rail	
FRONT ENTRY			
Steps	good		
Screens/windows	n/a		
Cover	none		
Floor	concrete		
Railings	n/a		
FENCES & GATES nor	e		
Туре			
Condition			
NOTES			

2. FOUNDATION / EXTERIOR / ROOF / INSULATION

	DESCRIPTION	DEFICIENCY	RECOMMENDATION	
FOUNDATION	'		<u>'</u>	
Basement walls	concrete			
Basement floor	concrete			
Floor joist	2x8 & 2x10			
Crawl space	none			
Slab on grade	none			
BASEMENT				
Stairs	good			
Railing	good			
Windows	wood			
Exterior door	none			
Electrical items	good			
EXTERIOR				
Wall structure	wood frame			
Wall covering	cement board	bad at fireplace pipe		
Outlets	good			
TRIM				
Soffits/fascia	cement board	stained around light in back		
Trim	vinyl/wood			
CHIMNEY				
Туре	metal fireplace			
Flashing	good where I could see it			
Сар	not visible from the ground			
Flues	1			
Mortar/brick condition	n/a			
Viewed from: ground with binoculars				
ROOF				
Style	gable	too steep to get on		
Material	shingles & metal	top two sections not visible from ground		
Flashings	good			
Gutters/downspouts	yes			

Vent stack boots	looks to be tarred		refresh seal
Viewed from: ground v	vith binoculars		
ATTIC			
Access	2 side doors/closets		
Roof frame	truss		
Vent type	none		
Visible insulation	spray foam/batt/cellulose		
Viewed from: access			
NOTES			

3. HEATING/COOLING

HEATING Lennox ANSI code 2004 Heating type forced air Approximate BTU's 88,000 Fuel type gas Condition good no carbon in Combustion air external Burners 4 Distribution duct Air filter 20x25x4 Humidifier flow thru AIR CONDITIONING Cooling type central air Approximate tons 3 Power 220 Condenser good Refrigerant lines good Condensate lines good FIREPLACE Location living room Fuel gas Fan none Damper good	ION DEFICIENCY	RECOMMENDATION		
Heating type forced air Approximate BTU's 88,000 Fuel type gas Condition good no carbon in external Burners 4 Distribution duct Air filter 20x25x4 Humidifier flow thru AIR CONDITIONING Cooling type central air Approximate tons 3 Power 220 Condenser good Refrigerant lines good Condensate lines good FIREPLACE Location living room Fuel gas Fan none		•		
Approximate BTU's 88,000 Fuel type gas Condition good no carbon in external Burners 4 Distribution duct Air filter 20x25x4 Humidifier flow thru AIR CONDITIONING Cooling type central air Approximate tons 3 Power 220 Condenser good Refrigerant lines good Condensate lines good FIREPLACE Location living room Fuel gas Fan none				
Fuel type Condition Combustion air Burners 4 Distribution Air filter AIR CONDITIONING Cooling type Approximate tons Power Condenser Refrigerant lines Condensate lines FIREPLACE Location Fuel Sound of Condenser Suppose Supp				
Condition good no carbon in external external Burners 4 Distribution duct Air filter 20x25x4 Humidifier flow thru AIR CONDITIONING Cooling type central air Approximate tons 3 Power 220 Condenser good Refrigerant lines good Condensate lines good FIREPLACE Location living room Fuel gas Fan none				
Combustion air external Burners 4 Distribution duct Air filter 20x25x4 Humidifier flow thru AIR CONDITIONING Cooling type central air Approximate tons 3 Power 220 Condenser good Refrigerant lines good Condensate lines good FIREPLACE Location living room Fuel gas Fan none				
Burners 4 Distribution duct Air filter 20x25x4 Humidifier flow thru AIR CONDITIONING Cooling type central air Approximate tons 3 Power 220 Condenser good Refrigerant lines good Condensate lines good FIREPLACE Location living room Fuel gas Fan none	onoxide			
Distribution duct Air filter 20x25x4 Humidifier flow thru AIR CONDITIONING Cooling type central air Approximate tons 3 Power 220 Condenser good Refrigerant lines good Condensate lines good FIREPLACE Location living room Fuel gas Fan none				
Air filter 20x25x4 Humidifier flow thru AIR CONDITIONING Cooling type central air Approximate tons 3 Power 220 Condenser good Refrigerant lines good Condensate lines good FIREPLACE Location living room Fuel gas Fan none				
Humidifier flow thru AIR CONDITIONING Cooling type central air Approximate tons 3 Power 220 Condenser good Refrigerant lines good Condensate lines good FIREPLACE Location living room Fuel gas Fan none				
AIR CONDITIONING Cooling type central air Approximate tons 3 Power 220 Condenser good Refrigerant lines good Condensate lines good FIREPLACE Location living room Fuel gas Fan none		change regularly		
Cooling type central air Approximate tons 3 Power 220 Condenser good Refrigerant lines good Condensate lines good FIREPLACE Location living room Fuel gas Fan none	shut down for summer/has leaked	keep element clean		
Approximate tons Power 220 Condenser good Refrigerant lines Condensate lines FIREPLACE Location L				
Power 220 Condenser good Refrigerant lines good Condensate lines good FIREPLACE Location living room Fuel gas Fan none				
Condenser good Refrigerant lines good Condensate lines good FIREPLACE Location living room Fuel gas Fan none				
Refrigerant lines good Condensate lines good FIREPLACE Location living room Fuel gas Fan none				
Condensate lines good FIREPLACE Location living room Fuel gas Fan none		keep fins clean		
FIREPLACE Location living room Fuel gas Fan none				
Locationliving roomFuelgasFannone				
Fuel gas Fan none				
Fan none				
Damper good				
	NOTES			

4. PLUMBING

	DESCRIPTION	DEFICIENCY	RECOMMENDATION	
MAIN LINE				
Water source	public			
Material	galvanized			
Well pump/pressure	n/a			
Shut off valve	basement			
Softener	none			
SUPPLY LINES				
Material	copper/pex			
WASTE LINES				
Material	pvc			
Traps/cleanouts	yes			
SPRINKLERS – visual in	spection only none			
Control box				
Backflow preventer				
Sprinkler pump				
HOSE FAUCETS		•		
Location	front & back			
Туре	frost free			
WATER HEATER			•	
Rheem power vent	ANSI code 2001 installed 3/	2008		
Туре	gas			
Gallons	50			
Safety valve/pipe	good			
Location	basement			
SUMP PUMP				
Location	basement			
Tested	no/ can't add water			
LIFT PUMP				
Location	laundry			
Tested	good			
NOTES				

5. ELECTRICAL

		a certon circoncist	
	DESCRIPTION	DEFICIENCY	RECOMMENDATION
SERVICE			
Overhead			
Underground	side of garage		
Outside ground	yes		
MAIN PANEL			
Location	basement		
Rating	200 amp		
Number of circuits	22		
main disconnect			
Location	side of garage		
Rating	200 amp		
Number of circuits	main breaker		
CONDUCTORS			
Service wire	aluminum		
Branch wire	romex		
PANEL NOTES			
Wiring	good		
Breakers	good		
Fuses	n/a		
Neutral	good		
Ground	good/to water pipe		
		NOTES	
ELECTRICAL ITEMS			
Fixture			
Fixture			
Wiring			
Wiring			
Outlet			
Outlet			
Covers			
Van's Home Inspection	1		2 nd C+

Covers		
001010		

6. INTERIOR

	DESCRIPTION	DEFICIENCY	RECOMMENDATION
DOORS			
Front entry	wood		
Rear/side entry	in main floor bathroom		
Slider	kitchen	screen slides hard	clean & adjust
French door	on porch	retractable screens broken	
Interior	good		
WINDOWS Jeldwen			
Туре	skylight on porch	2 pieces of trim missing	
Туре	casement/awning		
Туре			
INTERIOR WALLS			
Туре	drywall		
Туре			
Туре			
CEILINGS			
Туре	drywall		
Туре	wood		
Туре			
FLOORS			
Туре	wood		
Туре	tile	piece of tile not in place/porch	
Туре	carpet		
Туре			
INTERIOR FEATURES			
Ceiling fans	good		
Stairs	good		
Smoke detectors	hard wired	1 battery missing	put in new batteries
Carbon monoxide detectors		none	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
		NOTES	•

7. GARAGE/LAUNDRY

	DESCRIPTION	DEFICIENCY	RECOMMENDATION
GARAGE	·		· ·
Type: attached			
Floor	concrete		
Walls/ceilings	drywall		
Attic access	none		
Door to living space	good		
Exterior door	none		
Vehicle door	good		
Automatic opener/safeties	good safeties checked		
Faucet	none		
Electrical items	good		
		NOTES	
LAUNDRY			
Water piping	good		
120 volt outlet	yes		
240 Volt outlet	no		
Gas piping	good		
Dryer venting	good		
Sink	good/lift pump good		
		NOTES	

8. KITCHEN

	DESCRIPTION	DEFICIENCY	RECOMMENDATION		
GENERAL					
Counters	concrete				
Cabinets	good				
Window	none				
Flooring	tile				
ELECTRICAL					
Lighting	good				
GFCI Protection	yes				
SINK					
Sink	stainless steel				
Faucet	good				
Plumbing under	good	minor build up small sink drain			
sink	good	Tillior build up siriali sirik draili			
DISPOSAL	i				
Switch	back splash				
Condition	ok	noisy			
RANGE					
Fuel	gas				
Burners		right front not lighting			
Oven	good				
Fan/hood	down exhaust				
Vented to	outside				
DISHWASHER					
Location	under counter				
Drain line	to disposal				
Condition	good				
SPECIAL FEATURES					
Trash compactor	n/a				
Microwave	free standing				
Water purifier	Culligan	not getting water from faucet			
Instant hot water	n/a				
	NOTES				

9. MAIN FLOOR BATHROOM

	DESCRIPTION	DEFICIENCY	RECOMMENDATION			
TOILET						
Condition	good					
Flushing	good					
Comments:						
SINK						
Condition	good					
Faucet	good					
Drain	good					
Cabinet & counter	good					
Comments:						
ELECTRICAL						
Lighting	good					
GFCI protection	yes					
VENTILATION						
Fan		doesn't hold a piece of paper toilet paper				
Window	in shower	crank handle broken				
BATHTUB none		1				
Condition						
Faucet						
Drain						
Enclosure						
Comments:						
SHOWER	SHOWER					
Condition	good					
Faucet	good					
Drain	good					
Enclosure	tile					
Comments:						
NOTES						

10. UPPER BATHROOM

	DESCRIPTION	DEFICIENCY	RECOMMENDATION	
TOILET				
Condition	good			
Flushing	good			
Comments:				
SINK				
Condition	good			
Faucet	good			
Drain	good			
Cabinet & counter	good			
Comments:				
ELECTRICAL				
Lighting	good			
GFCI protection	yes			
VENTILATION				
Fan	good			
Window	in shower	painted shut		
BATHTUB none				
Condition				
Faucet				
Drain				
Enclosure				
Comments:				
SHOWER				
Condition	good			
Faucet	good			
Drain	good			
Enclosure	tile			
Comments:				
NOTES				

Van's Home Inspection Service
Ron Vander Velde